P. 003/017

## AMENDMENT TO THE SPECIFICATION

Please amend paragraph [00059] to state the following,

The Buskop Law Group, PC

[00059] FIG 7 shows bearing (42) in which both the longitudinal movement and the translational movement are taken by the same bearing with two load carrying sides. In order to keep the sliding bearing in the correct position resistance elements (63) and (64) are located in the fluid supply line (45) 65.

BEST AVAILABLE COPY

Attorney Docket: 1141111A Serial No: 10/685,981